

Date..... 05.01. 2010 No. of Pages (incl. this sheet) 1 Page..... 1 of..... 1

TO : M/S.DANWAYELECTRICAL &
MECHANICAL ENGINEERING LLC

OUR REF. : P-TR/AGJ/TM/ 17 / 09

FAX NO. : 04-266 4362

SUBJECT:

CE/448D/07
SUPPLY, INSTALLATION, TESTING &
COMMISSIONING OF EARTH
STATION & INTERNATIONAL CITY -
4 132/11KV SUBSTATIONS &
ASSOCIATED WORKS

ATTN : MR. H. NAGRAJ
SR. PROJECT MANAGER

132kV Cable Clamp

This has reference to your submission D337/7780/09 dated 24/12/2009 & our comments under:

- Submitted type test (40kA –1s) report on M/s. SSE make cable cleat (trefoil) for 132kV cable is found in order & the above cleat is acceptable for DEWA 132kV cables.
- However, the drawings submitted along with the report is found faded / unclear ; a legible / clear copy of aforesaid drawings shall be submitted for our records, please.

For your information & necessary action, please

JOSE A GEORGE

ASST. SENIOR MANAGER - PROJECT TRANSMISSION

